

IMPORTANT

If the engine is currently equipped with rocker cover studs, they can not be used with this gasket. They must be removed and the new bolts must be used. Failure to use the new bolts with this gasket will result in oil leakage.

Bolts sold separate ES 72135 (2 required)