




## INSTALLATION INSTRUCTIONS

Axle-Back Exhaust

49-46081

MAKE: Toyota  
MODEL: Land Cruiser  
YEAR: 2024  
ENGINE: L4-2.4L(t)



Item	Description	Part Number	Quantity
1	Over-Axle	05-244542	1
2	Tailpipe	05-244607	1
3	2-1/2" Band Clamp	05-41061	1
4	Screw, Flange Head: M10 X 1.25 X 30MM	03-50469	2

**aFe POWER recommends professional installation on this product.** Thoroughly inspect the aFe POWER exhaust system to make sure there is no damage from shipping (if damage is noted, immediately contact aFe POWER customer service). Allow time for your vehicle to cool down prior to installation. When working on your vehicle proceed with caution. Wear protective safety equipment; eye goggles and gloves to ensure a safe installation.

Install band clamps to proper torque specifications of 40-45 ft-lb.





## INSTALLATION INSTRUCTIONS

**Axle-Back Exhaust**

**MAKE:** Toyota  
**MODEL:** Land Cruiser  
**YEAR:** 2024  
**ENGINE:** L4-2.4L(t)

49-46081

- 
1. **(Read instructions prior to installation.)** It is recommended to not fully tighten the exhaust until it has been fully installed. Leave loose for adjustability.
  2. Secure vehicle on jack stands (refer to your manual for specified jack stand positions).
  3. For faster installation, spread out the parts of the exhaust alongside your vehicle as shown in the diagram above.
  4. Secure the stock exhaust with jack/stands.
  5. Bolt on aFe Over-Axle onto O.E muffler assy and use provide bolts and O.E nuts to install.
  6. Install the tailpipe onto the aFe over axle using provide band clamp.
  7. Install the tailpipe into the factory isolator.
  8. Ensure that all the components of the aFe POWER exhaust system are aligned and are at a safe clearance from all wires, hoses, brake lines, body parts, and tires.
  9. Start from the front of the aFe exhaust system and evenly tighten all clamps and fasteners.
  10. Start the vehicle and check for any leaks. If any leaks are found, determine cause and repair as necessary.
  11. Remove vehicle from jacks stands.
  12. It is recommended to re-tighten all clamps and hardware after 50-100 miles.